

# TREKU



## **Goi Coat Rack**

PRODUCT DATA SHEET

2307

1/3

**Model:** Goi


**Manufactured in:** Spain-Europe (EU)

**Designers:** Estudi Manel Molina

There are two versions of the rack: freestanding or wall-mounted. The hooks can be lacquered in any of our colours, and coupled with our woods and lacquers on the front of the rack, offering infinite different combinations, from serious and elegant to fun and fresh.

## 1. Measurements

---



Floor-standing



Wall mounted

## 2. Materials

---

**Body:** Solid beech wood varnished with polyurethane and finished with acrylic based lacquer

**Front:** MDF board covered with wood veneer. UV cured varnish in faces.

**Union bushing to the Wall:** 24 mm and 1.5 mm thick steel tube coated with epoxy paint.

**Metal structure:** 40 mm Steel tube with 6 mm thick steel base covered with epoxy paint.

## 3. Finishes

---

Treku Woods  
Treku Lacquers

## 4. Product maintenance

---

For cleaning use a cloth moistened with water. Do not use solvents or cleaning products.

## 5. Packaging and transportation

---

All our products are packaged for optimal protection (cardboard, foams and Styrofoam) and shipped with the greatest care.

## 6. Assembly instructions

---

All our products include assembly instructions for their correct installation.

See attached document.

For any technical question, do not hesitate to contact our technical department.

Units and chest of drawers are assembled at the factory.

## 7. Warranty

---

The products have 2 years guarantee as long as its installation is carried out by professionals of the sector and the use of the material is adequate. Treku accepts no liability for any incident arising from the mishandling of the materials supplied.

Wood, being a natural product, may have small differences in texture, color and pattern. Treku is not responsible for any minor differences that may arise.

Because of its natural origin, the wood with time may suffer differences in color and texture therefore the homogeneity of colors cannot be ensured in additional orders.